

Network Device Interpretation # 202413

Missing section header in NDcPP Appendix B

Status: *Active* *Inactive*

Date: *19-Aug-2024*

End of proposed Transition Period (to be updated after TR2TD process): *19-Aug-2024*

Type of Change: Immediate application Minor change Major change

Type of Document: *Technical Decision* *Technical Recommendation*

Approved by: *Network iTC Interpretations Team* *Network iTC*

Affected Document(s): *NDcPP v3.0e*

Affected Section(s): *B.6*

Superseded Interpretation(s): *None*

Issue:

Issue:

In NDcPP v3.0e, section B.6.3 for FTA_SSL_EXT is under section B.6 for Security Management (FMT). It seems that there should be a section B.7 for TOE Access (FTA) and B.6.3 for FTA_SSL_EXT should be moved under that as B.7.1.

Resolution:

To overcome the issue described in the 'Issue' section, the following changes shall be performed:

- A new chapter B.7 for TOE Access (FTA) shall be added.
- Chapter B.6.3 for FTA_SSL_EXT shall be moved under the newly created chapter B.7 as B.7.1.

Rationale:

The issue is obviously a mistake due to an oversight in the editorial process during generation of NDcPPv3.0e.

Further Action:

None

Action by Network iTC:

None